



Radii times 2

Drawing is mirrored

Crankshaft Center

Transmission Mounting Points

www.millersmule.com

100.0°

100.0°

21.5°

31.0°

3.099

3.099

3.421

3.693

2

1

2

1

B

B

A

A